

# Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
UPRC 13-110 (2025 Seasonal)	Spring	Marco Gonzalez	5/22/2025
Work Summary	Reclamation Type	Land Use	
Innerseeded site	Final Maint	Other	
One-Call Number	Red Zone Rep	Red Zone Date	

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance		No	Location(s): UPRC 13-110 Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: <b>21,780 sq ft</b> Seed Mix: <b>Sandy Soil 2 (10.00 lbs)</b> Crop Type: Soil Type: <b>Sandy</b> Stabilization Date: Seeding Date: <b>5/22/2025</b> Mulch: <b>None</b> Straw Bales: <b>NA</b> Soil Amendment Type: <b>None</b> Soil Amendment Rate: <b>NA</b> Imported Top Soil: <b>NA</b> Top Soil Source: <b>NA</b> General Notes: <b>Job oxrm1521</b>
---

PHOTOS





Photo Name: Seed Mix  
Description:





**Photo Name: Pre-Completion**

Description:





**Photo Name: Post-Completion**

Description:

