

Final Reclamation Inspection

April 30, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 319288

Inspection Document #: 718800244

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BERNARD E. TEETS #2
Location ID: 319288



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but bare ground and weedy annual vegetation remains at the site.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: BERNARD E. TEETS #2
Location ID: 319288



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: BERNARD E. TEETS #2
Location ID: 319288



Photo 5. Photo taken of the tank battery location, facing South. Photo illustrates that bare ground remains at the tank battery location and vegetation has not established from final reclamation activities.



Photo 6. Photo taken of the tank battery location, facing North. See comments under Photo 5.

Inspection Photos
Location Name: BERNARD E. TEETS #2
Location ID: 319288



Photo 7. Photo taken from the access road, southwest of the location, facing Northeast. Photo illustrates that disturbance remains along the access road.



Photo 8. Photo taken of the well location. Photo illustrates that bare ground remains at the location.



Inspection Photos
Location Name: BERNARD E. TEETS #2
Location ID: 319288



Photo 9. Photo taken of erosion north of the access road, directly east of Location ID # 331225. A small gully, approximately one foot across and 8 feet in length has formed. The access road is located to the top right corner of the image.

Inspection Photos
Location Name: BERNARD E. TEETS #2
Location ID: 319288



Photo 10. Photo taken of the reference area, south of the location, facing South. Photo illustrates perennial grass vegetation.