

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336158

Inspection Document #: 718800279

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-B/R-63N67W/20SENE
Location ID: 336158



Photo 1. Photo taken from the multi-well location, facing North. Photo illustrates that the well site meets Rule 1004 requirements.



Photo 2. Photo taken from the multi-well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: HSR-B/R-63N67W/20SENE
Location ID: 336158



Photo 3. Photo taken from the multi-well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the multi-well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: HSR-B/R-63N67W/20SENE
Location ID: 336158



Photo 5. Photo taken from the access road, facing Southeast towards the location. Photo illustrates that the access road has not been reclaimed. Gravel remains on the road and weedy annual vegetation dominates the location.



Photo 6. Photo taken of the access road, facing South. Photo illustrates that erosion is present along the side of the road (highlighted in red).

Inspection Photos
Location Name: HSR-B/R-63N67W/20SENE
Location ID: 336158



Photo 7. Photo taken of the access road, facing South. Photo illustrates that the access road has not been reclaimed and culverts remain along the road.



Photo 8. Photo taken of the access road, facing Northeast, towards the multi-well location. See comments under Photo 5.

Inspection Photos
Location Name: HSR-B/R-63N67W/20SENE
Location ID: 336158



Photo 9. Photo taken of the reference area, south of the multi-well location, facing East. Photo illustrates perennial grass vegetation.

