

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329337

Inspection Document #: 718800285

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-REDMOND #12-21
Location ID: 329337



Photo 1. Photo taken from the well location, facing North. Photo illustrates that the well site meets Rule 1004 requirements.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: HSR-REDMOND #12-21
Location ID: 329337



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: HSR-REDMOND #12-21
Location ID: 329337



Photo 5. Photo taken from the access road, facing West. Photo illustrates that the access road has been reclaimed, but patches of weedy growth remain and vegetation establishment does not meet Rule 1004 standards.



Photo 6. Photo taken of the access road, facing East towards the well site. See comments under Photo 5.

Inspection Photos
Location Name: HSR-REDMOND #12-21
Location ID: 329337



Photo 7. Photo taken of the tank battery location, facing South. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 8. Photo taken of the tank battery location, facing North. See comments under Photo 7.

Inspection Photos
Location Name: HSR-REDMOND #12-21
Location ID: 329337



Photo 9. Photo taken of the tank battery location, facing Southeast. Photo illustrates that a buried valve set for midstream equipment remains on location.



Photo 10. Photo taken of the reference area, northeast of the well site, facing Northeast. Photo illustrates perennial grass vegetation.

