

# Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329343

Inspection Document #: 718800290

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-WEIS #5-21  
Location ID: 329343



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows from seeding and straw mulch, but vegetation has not yet established to Rule 1004 standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: HSR-WEIS #5-21  
Location ID: 329343



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-WEIS #5-21  
Location ID: 329343



**Photo 5.** Photo taken from the tank battery location, facing South. Photo illustrates the operator has performed reclamation, with evidence of drill row seeding and straw mulch, but vegetation has not yet established to Rule 1004 standards.



**Photo 6.** Photo taken of the tank battery location, facing East. See comments under Photo 5.





Inspection Photos  
Location Name: HSR-WEIS #5-21  
Location ID: 329343



**Photo 7.** Photo taken of the tank battery location, facing Northeast. Photo illustrates midstream equipment remains on location.



**Photo 8.** Photo taken of the reference area, south of the location, facing Southeast. Photo illustrates perennial grass vegetation.

