

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 445406

Inspection Document #: 718800298

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PSC 22-11 & 32-11A O SA
Location ID: 445406



Photo 1. Photo taken from the tank battery location, facing North. Photo illustrates that final reclamation activities have not taken place and gravel and bare ground remains at the location.



Photo 2. Photo taken of the tank battery location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: PSC 22-11 & 32-11A O SA
Location ID: 445406



Photo 3. Photo taken from the tank battery location, facing East. Photo illustrates that final reclamation activities do not appear to have taken place and the meter house remains on location.



Photo 4. Photo taken from the well location, facing East. Photo illustrates the meter house which remains on site and is no longer in use.



Inspection Photos
Location Name: PSC 22-11 & 32-11A O SA
Location ID: 445406



Photo 5. Photo taken of the reference area, west of the location, facing Northeast. Photo illustrates perennial grass vegetation.

