

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330209

Inspection Document #: 718800315

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: NORGREN #14-9J7
Location ID: 330209



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: NORGREN #14-9J7
Location ID: 330209



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: NORGREN #14-9J7
Location ID: 330209



Photo 5. Photo taken from the access road, facing East towards the well location. Photo illustrates that final reclamation has not taken place along the access road.



Photo 6. Photo taken of the access road, facing East. See comments under Photo 5.

Inspection Photos
Location Name: NORGREN #14-9J7
Location ID: 330209



Photo 11. Photo taken of the reference area, north of the well location, facing Northeast. Photo illustrates perennial grass vegetation.

