

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 446129

Inspection Document #: 718800322

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NORGREN 14-9J7, 14-16J7 O SA

Location ID: 446129



Photo 1. Photo taken from the tank battery location, facing West. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the tank battery location, facing South. See comments under Photo 1.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718800322

Inspection Photos

Location Name: NORGREN 14-9J7, 14-16J7 O SA

Location ID: 446129



Photo 3. Photo taken of the tank battery location. Photo illustrates monitoring observation wells remain on location.



Photo 4. Photo taken of the reference area, north of the tank battery location, facing Northwest. Photo illustrates perennial grass vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718800322