

Final Reclamation Inspection

May 15, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329239

Inspection Document #: 718800330

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-PETRIE #3-7
Location ID: 329239



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: HSR-PETRIE #3-7
Location ID: 329239



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: HSR-PETRIE #3-7
Location ID: 329239



Photo 5. Photo taken from the access road, facing Southeast towards the well location. Photo illustrates that vegetation has not established to Rule 1004 standards along the access road.



Photo 6. Photo taken of vegetation along the access road. Photo illustrates that cheatgrass (*Bromus tectorum*) is present across the location and is a List C noxious weed species.



Inspection Photos
Location Name: HSR-PETRIE #3-7
Location ID: 329239



Photo 7. Photo taken of the tank battery location, facing South. Photo illustrates that the tank battery remains in use for another TA well site.



Photo 8. Photo taken of the reference area, south of the well site, facing South. Photo illustrates the site is dominated by perennial grass vegetation and cheatgrass (*Bromus tectorum*).