

Final Reclamation Inspection

May 15, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329223

Inspection Document #: 718800333

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-PARKMAN #6-7
Location ID: 329223



Photo 1. Photo taken from the well location, facing North. Photo illustrates final reclamation has taken place, but cheatgrass (*Bromus Tectorum*) is present and must be managed on the site (see Photo 5).



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: HSR-PARKMAN #6-7
Location ID: 329223



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: HSR-PARKMAN #6-7
Location ID: 329223



Photo 5. Photo taken of vegetation at the well site. Photo illustrates that cheatgrass (*Bromus tectorum*) is present across the location and is a List C noxious weed species.



Photo 6. Photo taken from the access road, facing West towards the well location. Photo illustrates that vegetation has not established to Rule 1004 standards along portions of the access road.



Inspection Photos
Location Name: HSR-PARKMAN #6-7
Location ID: 329223



Photo 7. Photo taken from the southern edge of the access road, facing South. Photo illustrates that there is stormwater erosion running along the edge of the access road and fencing is in place and in disrepair.



Photo 8. Photo taken of the northern edge of the access road, facing northeast. See comments under Photo 7.



Inspection Photos
Location Name: HSR-PARKMAN #6-7
Location ID: 329223



Photo 9. Photo taken from the access road, facing northwest, along the Northern edge of the road. Photo illustrates weedy annual vegetation (*Salsola tragus*) and erosion along the edge of a portion of the access road.



Photo 10. Photo taken of vegetation along the access road. Photo illustrates that cheatgrass (*Bromus tectorum*) is present across the location and is a List C noxious weed species.



Inspection Photos
Location Name: HSR-PARKMAN #6-7
Location ID: 329223



Photo 11. Photo taken of the tank battery location, facing South. Photo illustrates that the tank battery remains in use for another TA well site.



Photo 12. Photo taken of the reference area, north of the well site, facing North. Photo illustrates the site is dominated by perennial grass vegetation.

