

Final Reclamation Inspection

May 15, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329386

Inspection Document #: 718800345

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DECHANT #D 7-10
Location ID: 329386



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DECHANT #D 7-10
Location ID: 329386



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DECHANT #D 7-10
Location ID: 329386



Photo 5. Photo taken from the access road, facing West towards the well location. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards.



Photo 6. Photo taken from the access road, facing Northeast away from the well location. See comments under Photo 5.



Inspection Photos
Location Name: DECHANT #D 7-10
Location ID: 329386



Photo 7. Photo taken from the reference area, northwest of the well location, facing Northwest. Photo illustrates perennial grass vegetation as well as the presence of cheatgrass (*Bromus tectorum*).