

# Final Reclamation Inspection

May 15, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 330113

Inspection Document #: 718800349

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DECHANT #D 7-15  
Location ID: 330113



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that the location does not meet Rule 1004 reclamation standards as bare ground remains across the location.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: DECHANT #D 7-15  
Location ID: 330113



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.





Inspection Photos  
Location Name: DECHANT #D 7-15  
Location ID: 330113



**Photo 5.** Photo taken from the access road, facing West towards the well location. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards. Cheatgrass (*Bromus tectorum*) is present across the access road and is a List C noxious weed species.



**Photo 6.** Photo taken from the access road, facing East away from the well location. See comments under Photo 5.





Inspection Photos  
Location Name: DECHANT #D 7-15  
Location ID: 330113



**Photo 7.** Photo taken from the reference area, south of the well location, facing South. Photo illustrates perennial grass vegetation.

