

Final Reclamation and Stormwater Inspection

May 21, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320576

Well Name: CO STATE A #24-36

Inspection Document #: 718600603

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: CO STATE A #24-36
Location ID: 320576



Photo 1. Looking east down the access road towards the well location. Access road vegetation is primarily undesirable weed russian thistle and list C noxious weed field bindweed. Little to no desirable vegetation is present on the access road.



Photo 2. Photo taken at midpoint of access road looking east. Illustrating undesirable weedy vegetation coverage and difference in vegetation compared to reference area.



Inspection Photos
Location Name: CO STATE A #24-36
Location ID: 320576



Photo 3. Looking east across the well location. Vegetation on location is primarily undesirable weedy vegetation russian thistle and kochia. Desirable vegetation establishment appears to be very poor across location.



Photo 4. Looking north from the wellbore. See photo 3 comments.



Inspection Photos
Location Name: CO STATE A #24-36
Location ID: 320576




Photo 5. Looking west from the wellbore. See photo 3 comments.



Photo 6. Looking south from the wellbore. See photo 3 comments.



Inspection Photos
Location Name: CO STATE A #24-36
Location ID: 320576



Photo 7. Aerial photo taken Apr 2, 2024. Before reclamation activity (red circle).



Photo 8. Aerial photo taken Apr 30, 2024. Appears that reclamation was conducted on this location (red circle) and several others in the area.



Inspection Photos

Location Name: CO STATE A #24-36

Location ID: 320576



Photo 9. Reference vegetation to the north of the location.