

Inspection Photos
Location: Jackson 04 L4 3154
Location ID: 488237
API # 05-071-09945



Photo 1 –Well placard

Photo 2 – Wellhead

Inspection Photos
Location: Jackson 04 L4 3154
Location ID: 488237
API # 05-071-09945



Photo 3 – Snow fence not maintained.

Photo 4 – Debris, trash on location