

Inspection Photos

May 14th, 2025

Operator: Highpoint Operating - 10071

Location ID: 322140

Inspection Document #: 714002182

Dolores County, CO

Township: SWSW 18 39N 17W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neely 13H-18-39-17
Location ID: 322140

May 14, 2025
179° S





Inspection Photos
Location Name: Neely 13H-18-39-17
Location ID: 322140



Photo 3. Photos taken from the center of the disturbance; left photo facing north , right photo facing west. Note: vegetation density does not appear consistent with adjacent corner crop areas (see photo #7).

Inspection Photos
Location Name: Neely 13H-18-39-17
Location ID: 322140



Photo 4. Evidence of remnant gravel that remains on the project area.

May 14, 2025
307° NW



Photo 5. View of layering soils suggesting compacted soils at the location.



May 14, 2025
286° W



Photo 6. Russian Olive observed at the center of the project area.

May 14, 2025
77° E



Photo 7. View of adjacent corner crop reference area.