



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Location sign.

Apr 30, 2025 2:26:11 PM
+39.4677N -108.2443W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Point of release.

Apr 30, 2025 2:28:24 PM
+39.4679N -108.2446W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Point of release.

Apr 30, 2025 2:28:43 PM
+39.4679N -108.2446W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Point of release.

Apr 30, 2025 2:31:47 PM
+39.4680N -108.2446W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Area where fluids ran down a Stormwater BMP drain pipe to the lower roadside bar ditch.

Apr 30, 2025 2:29:11 PM
+39.4678N -108.2446W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Area where fluids entered
the lower roadside bar
ditch.

Apr 30, 2025 2:24:49 PM
+39.4677N -108.2447W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Area where fluids
traveled down the bar
ditch.

Apr 30, 2025 2:23:44 PM
+39.4678N -108.2452W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Area where fluids
traveled down to the
irrigation ditch.

Apr 30, 2025 2:38:21 PM
+39 4675N -108.2455W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Area where the hydrovac crew were remediating impacts adjacent to the irrigation ditch.

Apr 30, 2025 3:08:37 PM
+39.4673N -108.2454W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Apparent oil stain in the area where the hydrovac crew was working.

Apr 30, 2025 4:30:01 PM
#39.4674N #108.2456W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Irrigation pond.

Apr 30, 2025 2:39:55 PM
+39.4673N -108.2453W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Apparent sheen on the surface of the irrigation pond.

Apr 30, 2025 3:54:21 PM
+39.4672N -108.2453W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Boom adjacent to the inlet of the pond to contain the sheen.

Apr 30, 2025 4:23:59 PM
+39.4672N -108.2454W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Area adjacent to the
outlet of the irrigation
pond.

Apr 30, 2025 3:02:31 PM
+39.4669N -108.2450W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Conn Creek.

Apr 30, 2025 3:19:26 PM
+39.4673N -108.2462W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pond 10
Facility ID: 159504
Spill/Release ID: 489978
Inspection Date: 4/30/2025

Conn Creek.

Apr 30, 2025 3:19:18 PM
+39.4673N -108.2462W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources