

Inspection Photos

API: 063-06292

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 5/28/2025

County: KIT CARSON



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the former wellsite. The area vegetated was not in cropland due to abandoned risers that were in the way.



Inspection Photos



Photo 2. Facing northeast where risers were removed. This area can now be planted back into cropland.

