

Inspection Photos

API: 063-06049

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 5/28/2025

County: KIT CARSON



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north where pipe riser has been removed. Disturbance area will need to be reclaimed.



Inspection Photos



Photo 2. Facing east where associated pipe riser was removed. There is subsidence and topsoil will be need to regrade this area.



Inspection Photos



Photo 3. Facing southeast toward the area of the former wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. There are a few small bare areas approximately 10'x2' which may have impacted soils preventing vegetation establishment.



Inspection Photos



Photo 5. There are a few small bare areas which may have impacted soils preventing vegetation establishment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing northwest at the former wellsite.



Inspection Photos



Photo 7. Facing south toward the surrounding undisturbed pasture consisting of Blue grama, Buffalo grass, and Six weeks fescue.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources