

Inspection Photos

API: 063-06349

Operator: **H2E OPERATIONS LLC**

Inspection Date: 5/28/2025

County: KIT CARSON



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at the beginning of the former access road. The cattleguard and perimeter fence have not been removed.



Inspection Photos



Photo 2. Facing east at the location . The perimeter fence remains around the location and is in disrepair.



Inspection Photos



Photo 3. Center of the location facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos




Photo 4. Center of the location facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Center of the location facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Center of the location facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources