

Inspection Photos

API: 017-07112

Operator: **P O & G OPERATING LLC**

Inspection Date: 5/28/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest at the beginning of the access road. There is vehicle traffic going around the cattleguard causing widening of the road and unnecessary surface disturbance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 2. Facing south along the access road. The access road is rutted and not maintained in this area. Vehicle are widening the road at this area.



Inspection Photos



Photo 3. The culvert along the access road near the wellsite has washed out and needs to be repaired. Previous CA was not completed.



Inspection Photos



Photo 4. Drone aerial photo facing southeast at the location.



Inspection Photos



Photo 5. Drone aerial photo facing east toward the location. There is impacted growth approximately 150' downhill from the wellhead.

