

WELL NAME: SPARROWHAWK 22-12 TR, API #: 071-08979, INSP. # 716301084



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: AREA OF IMPACTED SOIL/GRAVEL ALONG THE HYDRO. LINES FROM COMPRESSOR TO DRIVEHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 6/15/2025.



PHOTO 5: OILY WASTE IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 6/5/2025.



PHOTO 6: OILY WASTE IN PRIME MOVER SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 6/5/2025.