

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SENW

Location ID: 335661

Date: 5/22/2025



Location – Photo #09114



Location – Photo #09119

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SENW

Location ID: 335661

Date: 5/22/2025



Location – Photo #09121



Location – Photo #09120



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SENW

Location ID: 335661

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09115



Illegible Wellhead Sign – Photo #09116

## Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SENW

Location ID: 335661

Date: 5/22/2025



Illegible Battery Sign – Photo #09117



Illegible Battery Sign – Photo #09118

