

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 5/22/2025



Location Overview – Photo #09094



Location – Photo #09110

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 5/22/2025



Location – Photo #09107



Location – Photo #09099




Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 5/22/2025



Illegible Tank Label – Photo #09106



Illegible Battery Sign – Photo #09098

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09111



Illegible Wellhead Sign – Photo #09112

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09113



Damaged Fencing – Photo #09108

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 5/22/2025



Stored Supplies – Photo #09100



Stored Supplies/Wildlife Entry Hazard – Photo #09104

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 5/22/2025



Stored Supplies/Wildlife Entry Hazard – Photo #09105