

Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Jun 5, 2025 13:07:36
37.10762N 107.75393W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Jun 5, 2025 13:07:43
37.10766N 107.75390W



Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Jun 5, 2025 13:07:54
37.10767N 107.75395W



Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Jun 5, 2025 13:08:23
37.10774N 107.75391W



Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Wildlife netting is inadequate. Gaps in netting are present.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Stained soil/gravel observed in previous inspection has been remediated. Wellhead appears to have small leak as evidenced by salt and oil staining of wellhead.

Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Jun 5, 2025 13:13:54
37.10777N 107.75435W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

**Wellhead appears to have small leak as evidenced by salt
and oil staining of wellhead.**

Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



Jun 5, 2025 13:13:57
37.10777N 107.75435W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Box in disrepair.

Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Location Name: SLUGGER-N33N8W/18NENE

Location ID #: 333801

