

Final Reclamation and Stormwater Inspection

June 4, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 320457

Location Name: MCELWAIN #11-17

Inspection Document #: 718600649

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCELWAIN #11-17
Location ID: 320457



Photo 1. Looking east from fallow cropland across cogis location.



Photo 2. Looking from cogis location. The gps location appears to be incorrect. It appears that significant earthworks were conducted over the location.



Inspection Photos
Location Name: MCELWAIN #11-17
Location ID: 320457



Photo 3. Looking north from the cogis location towards the actual location.



Photo 4. Looking south from the west side of wellbore location.

Inspection Photos
Location Name: MCELWAIN #11-17



Photo 5. Google earth aerial photo taken 06/2020. Access road and well location are in cropland. GPS data of wellbore location appears to be 125 ft off from imagery.

Inspection Photos
Location Name: MCELWAIN #11-17
Location ID: 320457




Photo 6. Google earth aerial photo taken 03/2025. Location appears to be located in land use change with significant earthworks conducted. Access road is present in cropland.

