

Final Reclamation and Stormwater Inspection

Date: 06/10/2025

Operator: RAMPART ENERGY COMPANY - 5685

Location ID: 387264

Inspection Document #: 718700463

Logan County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Schrader J12
Location ID: 387264



Photo 1. It appears that the piping observed in previous inspections has been removed.

Inspection Photos
Location Name: Schrader J12
Location ID: 387264



Photos 2 & 3. Taken near the former well location. It appears that the concrete base has been removed. However, the reclaimed area does not appear to be progressing towards reclamation standards with evidence of bare/unstabilized soils and undesirable vegetation (CO List C Noxious Weed - Cheatgrass, and kochia).

Inspection Photos
Location Name: Schrader J12
Location ID: 387264



Photos 4 & 5. Taken near the former well location facing south (Photo 4; left) and west (Photo 5; right). See Photos 2 & 3 for additional information.

Inspection Photos
Location Name: Schrader J12
Location ID: 387264



Photo 6. Adjacent reference area northeast of the former well location.