

Inspection Photos
Location: Rhoades 5-6
Location ID: 321656
API # 05-017-06629



Photo 1 –Well placard



Photo 2 – Wellhead, Impacted soils

Inspection Photos
Location: Rhoades 5-6
Location ID: 321656
API # 05-017-06629




Photo 3 – Impacted soils



Photo 4 – Impacted soils