



## Inspection Photos

Location: Speaker Unit Compressor

Location ID: 412172

Spill ID # 488536 and Spill ID 489279



**Photo 3 – Area identified to have impacted soils, FIR  
Doc # 701104140**

**Photo 4 – Area identified to have impacted soils, FIR  
Doc # 701104140, Spill ID 489279**

## Inspection Photos

Location: Speaker Unit Compressor

Location ID: 412172

Spill ID # 488536 and Spill ID 489279



**Photo 5 – Area identified to have impacted soils, FIR Doc # 701104140**

**Photo 6 – Excavation area identified in FIR Doc # 713602155, Spill ID 488536**

## Inspection Photos

Location: Speaker Unit Compressor

Location ID: 412172

Spill ID # 488536 and Spill ID 489279



**Photo 7 – Impacted spoil pile**

**Photo 8 – Impacted spoil pile**