

Inspection Photos
Location Name: Fonte 1-22
API Number: 125-06294



1. Lease sign at well location.



2. View of wellhead. Note ground wet around wellhead from leak at packing.

Inspection Photos
Location Name: Fonte 1-22
API Number: 125-06294



3. Gas Meter inside Meter Box.



4. View of Thistle on location.

Inspection Photos
Location Name: Fonte 1-22
API Number: 125-06294



5. Well location overview. Note Anchor missing marker,



6. Well location overview.