

Inspection Photos
Location Name: Fonte 23-15
API Number: 125-07596



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Fonte 23-15
API Number: 125-07596



3. Dehydrator and Gas Meter inside Meter Box.



4. Well location overview.