

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8626 From entrance to location




Photo # 8627 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8628 Location



Photo # 8629 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8630 Location



Photo # 8631 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8632 Holes in liner/liner needs maintenance



Photo # 8933 Holes in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8634 Hole in liner/liner needs maintenance



Photo # 8635 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8636 Holes in liner/liner needs maintenance



Photo # 8637 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8638 Hole in liner/liner needs maintenance



Photo # 8639 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8640 Hole in liner/liner needs maintenance



Photo # 8641 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Jun 12, 2025 at 2:12:49 PM
CO



Jun 12, 2025 at 2:12:32 PM
CO

Photo # 8642 Liner deteriorating/liner needs maintenance

Photo # 8643 Liner deteriorating/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Jun 12, 2025 at 2:13:02 PM
CO



Jun 12, 2025 at 2:13:08 PM
CO

Photo # 8644 Liner deteriorating/liner needs maintenance

Photo # 8645 Liner deteriorating/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location #: 311622



Photo # 8646 Liner deteriorating/liner needs maintenance



Photo # 8647 Debris