

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GENTRY-66S92W/17SESE

Location ID: 311695

Date: 6/11/2025



Jun 11, 2025 at 12:03:18
Silt CO 81652
United States

Location Overview – Photo #09253



Jun 11, 2025 at 12:04:54
Silt CO 81652
United States

Location/Weeds – Photo #09257

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GENTRY-66S92W/17SESE

Location ID: 311695

Date: 6/11/2025



Location/Weeds – Photo #09261



Location/Weeds – Photo #09270

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GENTRY-66S92W/17SESE

Location ID: 311695

Date: 6/11/2025



Location/Weeds – Photo #09262



Damaged/Illegible Battery Sign – Photo #09271



Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GENTRY-66S92W/17SESE

Location ID: 311695

Date: 6/11/2025



Weeds – Photo #09255



Weeds – Photo #09256

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GENTRY-66S92W/17SESE

Location ID: 311695

Date: 6/11/2025



Weeds – Photo #09263



Weeds – Photo #09264