

Inspection Photos  
Location Name: Short 1-23  
API Number: 125-06134



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Short 1-23**  
**API Number: 125-06134**



**3. Gas Meter inside Meter Box.**



**4. Well location overview. Note Thistle in lower right corner of frame.**