

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10 (K4B2) Pad

Location #: 334605



Photo # 8316 From entrance to location




Photo # 8317 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10 (K4B2) Pad

Location #: 334605



Photo # 8318 Location




Photo # 8319 Location





## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10 (K4B2) Pad

Location #: 334605



Photo # 8320 Location



Photo # 8321 Open ended load line

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10 (K4B2) Pad

Location #: 334605



**Photo # 8322 Emergency phone # on sign at separators incorrect/# is disconnected & not in service/not in compliance with CECMC rules.**



**Photo # 8323 Emergency phone # on sign at separators incorrect/# is disconnected & not in service/not in compliance with CECMC rules.**



## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10 (K4B2) Pad

Location #: 334605



**Photo # 8324 Emergency phone # on sign at separators incorrect/# is disconnected & not in service/not in compliance with CECMC rules.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources