

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7870 From entrance to location




Photo # 7871 Location

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7872 Location




Photo # 7873 Location

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7874 Location



Photo # 7875 Staining

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7876 Staining



Photo # 7877 Weeds in secondary containment

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7878 Weeds in secondary containment



Photo # 7879 Unused flowline does not comply with CECMC 600 & 1100 series rules

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7880 Unused flowline does not comply with CECMC 600 & 1100 series rules



Photo # 7881 Unused flowline does not comply with CECMC 600 & 1100 series rules

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7882 Possible unused flowline does not comply with CECMC 600 & 1100 series rules (Additionally open ended piping near the wellhead also constitutes a wildlife hazard)



Photo # 7883 Possible unused flowline does not comply with CECMC 600 & 1100 series rules (Additionally open ended piping near the wellhead also constitutes a wildlife hazard)

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7884 Hounds Tongue/undesirable plant species in the interim area



Photo # 7885 Hounds Tongue/undesirable plant species in the interim area

Inspection/Audit Photos

Location Name: LARAMIE ENERGY LLC CASCADE CREEK 610-24-43 Pad

Location #: 324314



Photo # 7886 Plumbless Thistle/undesirable plant species in the interim area



Photo # 7887 Plumbless Thistle/undesirable plant species in the interim area