



Signage with emergency contact number is visible. Labels/placards are legible.




ECMC
Environmental
Field Inspection



Lowe Tank Battery
© 30-May-25 12:10:33 PM
ECMC Environmental Inspection

Animal burrows are visible in multiple areas of the shared production tank and produced water vessel containment berm. A plastic pipe connecting the production tank to the emission control device is visible; the pipe is attached to fence posts by tape.



Low Tank Battery
© 30-May-25 12:11:26 PM
ECMC Environmental Inspection

WGS84 38.69440, -102.42097 Δ ^m_{±4m} 1329 \triangle [°]_{±11} NE52



ECMC
Environmental
Field Inspection



Lowe Tank Battery
© 30-May-25 12:11:40 PM
ECMC Environmental Inspection



ECMC
Environmental
Field Inspection

Lowe Tank Battery
© 30-May-25 12:12:39 PM
ECMC Environmental Inspection

Animal burrows are visible in multiple areas of the separator containment berm.

WGS84 38.69422, -102.42084 $\pm 8\text{ft}$ $\pm 3\text{m}$ 1329 ± 11 °T N350



ECMC
Environmental
Field Inspection



Lowe Tank Battery
© 30-May-25 12:13:20 PM
ECMC Environmental Inspection



ECMC
Environmental
Field Inspection



Lowe Tank Battery
© 30-May-25 12:14:05 PM
ECMC Environmental Inspection

Labels/placards are legible.



Lowe Tank Battery
30-May-25 12:14:21 PM
ECMC Environmental Inspection

ECMC
Environmental
Field Inspection

