

# Inspection Photos

05/30/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 334786

**Inspection Doc:** 719200005

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334786



**Photo 1:** Photos are taken from the central portion of the Location looking at the western pad. Photos provide an overview of the Location looking southwest and northwest, respectively. Location has been reduced to areas reasonably needed for production; vegetation appears to be progressing towards 1003 Standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334786



**Photo 2:** Photos are taken from the eastern pad of the Location looking east and southwest, respectively. The eastern pad is showing signs of light sediment tracking. BMP's show signs of disrepair; maintenance advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334786



**Photo 3:** Photo taken from between the separator equipment on the west end of the Location. Photos shows riser associated with abandoned wells/equipment remaining on the Location. The riser requires cutting, capping and removal.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334786



**Photo 4:** Photo taken from the edge of the working pad surface and interim areas of the Location. Photo example showing bindweed, cheatgrass and redstem fillaree have established on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334786



**Photo 4:** Photo taken from the edge of the working pad surface and interim areas of the Location. Photo example showing houndstongue and tamarisk have established at the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334786



**Photo 5:** Photo taken from the interim area on the northern end of the Location. Photo shows a non-functional wattle; removal is advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334786



**Photo 6:** The tank battery liner appears to be aging and may need replaced soon.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources