

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McPherson/A Pad

Location ID: 335539

Date: 6/11/2025



Location Overview – Photo #09297



Location – Photo #09298

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McPherson/A Pad

Location ID: 335539

Date: 6/11/2025



Location – Photo #09304



Location – Photo #09300

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McPherson/A Pad

Location ID: 335539

Date: 6/11/2025



Location – Photo #09299



PRV Terminates in Unsafe Manner – Photo #09302

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McPherson/A Pad

Location ID: 335539

Date: 6/11/2025



PRV Terminates in Unsafe Manner – Photo #09303