

# Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GV 23-34 PAD

Location ID: 335261

Date: 06/9/2025



Jun 9, 2025 at 2:22:39 PM  
+39.479293,-108.088588 ±8.40m  
Parachute



Jun 9, 2025 at 2:43:00 PM  
+39.479516,-108.088451 ±3.69m  
Parachute

TEP Rocky Mountain LLC

970-285-9377  
GV 23-34 PAD

COC NONE	API
GV 23-34	05-045-06640
GM 234-34	05-045-10376
GM 443-34	05-045-10374
GM 543-34	05-045-10375
GM 643-34	05-045-10377

NESE SEC 34/T6S/R96W  
GARFIELD COUNTY, CO  
EMS 911  
ACCESS FROM: CR. 215

Photo # 8055 Entrance to location

Photo # 8081 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GV 23-34 PAD

Location ID: 335261

Date: 06/9/2025



Photo # 8057 Location



Photo # 8087 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GV 23-34 PAD

Location ID: 335261

Date: 06/9/2025



Photo # 8080 Location

Photo # 8087 NW corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GV 23-34 PAD

Location ID: 335261

Date: 06/9/2025



Photo # 8088 NE corner of location



Photo # 8089 SE corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GV 23-34 PAD

Location ID: 335261

Date: 06/9/2025



Photo # 8091 SE corner of location



Photo # 8086 Open ended load line

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GV 23-34 PAD

Location ID: 335261

Date: 06/9/2025



Photo # 8096 Unmarked deadman



Photo # 8079 Debris