

Inspection Photos
Location: Arapahoe Unit Tank Battery #Sec. 26
Location ID: 480416, Spill ID 488411



Photo 1 – Placard with animal burrow in berm



Photo 2 – Facing North viewing spill location on East side of tank battery



Photo 3 – Pink Flags and plastic sampling bags



Inspection Photos
Location: Arapahoe Unit Tank Battery #Sec. 26
Location ID: 480416, Spill ID 488411



Photo 4 – Facing North on east side of AST more plastic sampling bags



Photo 5 – Facing West on West side of Tanks with more plastic sampling bags



Photo 6 – Facing Northeast viewing unlabeled stockpiles and plastic sampling bags



Inspection Photos
Location: Arapahoe Unit Tank Battery #Sec. 26
Location ID: 480416, Spill ID 488411



Photo 7 – Unlabeled stockpiles with inadequate berms



Photo 8 – Adequate wildlife netting



Photo 9 – Facing North, unused equipment