

**Inspection Photos**  
**Location: Arapahoe Unit Tank Battery #Sec. 27**  
**Location ID: 480511, Spill ID 489069**



**Photo 1 – Placard**



**Photo 2 – Facing Southeast  
unused equipment**



**Photo 3 – Facing East, open  
excavation no fencing**





**Inspection Photos**  
**Location: Arapahoe Unit Tank Battery #Sec. 27**  
**Location ID: 480511, Spill ID 489069**



**Photo 4 – Facing South by Southwest, open excavation no fencing**



**Photo 5 – Facing West open excavation**



**Photo 6 – Facing South by Southwest, open excavation**





**Inspection Photos**  
**Location: Arapahoe Unit Tank Battery #Sec. 27**  
**Location ID: 480511, Spill ID 489069**



**Photo 7 – Line Marker**



**Photo 8 – Unlabeled Stockpile**



**Photo 9 – Facing South , open excavation**