

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8577 Entrance to location



Photo # 8595 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8578 Location



Photo # 8586 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8591 Location



Photo # 8594 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8612 SE corner of location



Photo # 8613 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8614 NW corner of location



Photo # 8615 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8579 Wellhead signs are not legible



Photo # 8580 Wellhead signs are not legible

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8581 Wellhead signs are not legible



Photo # 8582 Wellhead signs are not legible

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8592 Debris



Photo # 8593 Debris

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8608 Debris



Photo # 8610 Debris

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8605 Open ended load line



Photo # 8606 Open ended load lines

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8607 Open ended load line




Photo # 8619 Tank on location not in use/unused equipment

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC SG 13-35 PAD

Location ID: 421060

Date: 06/16/2025



Photo # 8603 Tank on location not in use/unused equipment




Photo # 8604 Tank label is weathered & cracking also contains inaccurate info/not in compliance with CECMC rules