

Inspection Photos

API: 009-06172

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 6/16/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing west toward the location. A crop cover has established at the former wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 2. Drone aerial photo facing east toward the location. A crop cover has established at the former wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06172 | Date: 6/16/2025

Inspection Photos



Photo 3. Drone aerial photo facing toward the offsite tank battery location 550 ft. from the wellsite. There are bare areas and undesirable weeds. This area has not been reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06172 | Date: 6/16/2025

Inspection Photos



Photo 4. Abandon pipe riser has not been removed from the associated tank battery site. Operator must work with midstream for removal.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06172 | Date: 6/16/2025