

# Inspection Photos

June 12th, 2025

Operator: Kinder Morgan

Location ID: 313474

Inspection Document #: 714002218

Montezuma County, CO

Township: NESE 31 38N 19W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Moqui 1  
Location ID: 313474

June 12, 2025  
347° N



**Photo 2.** View of the project area taken from the southern edge facing center.

Inspection Photos  
Location Name: Moqui 1  
Location ID: 313474

June 12, 2025  
328° NW



**Photo 2.** View of access road which has not been revegetated per 1004 rules.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 083-06243

Inspection Photos  
Location Name: Moqui 1  
Location ID: 313474

June 12, 2025  
125° SE



**Photo 3.** View of adjacent reference area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 083-06243