

Final Reclamation and Stormwater Inspection

June 12, 2025

Operator: CORAL PRODUCTION CORP - 20275

Location ID: 317307

Well Name: LINDA #1

Inspection Document #: 718600668

Washington County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LINDA #1
Location ID: 317307



Photo 1. Looking east across the entrance and former tank battery. Undesirable weed kochia is present throughout the location. Location has not been recontoured and pits remain on location.



Photo 2. Picture taken from the southwest corner of the south pit. T posts and metal debris are present in the pit.



Inspection Photos
Location Name: LINDA #1
Location ID: 317307



Photo 3. Looking east across the skim pit area.




Photo 4. Looking north across the northeast pit. Metal pipe is present in the pit.



Inspection Photos
Location Name: LINDA #1
Location ID: 317307



Photo 5. Looking northwest across the northwest pit.



Photo 6. Looking west down the access road towards the wellhead.



Inspection Photos
Location Name: LINDA #1
Location ID: 317307



Photo 7. Looking southwest across the wellbore area. Electrical equipment and posts remain on location.



Photo 8. Looking northeast across the wellhead area. Wood debris, pipe and exposed wires are present on location.



Inspection Photos
Location Name: LINDA #1
Location ID: 317307



Photo 9. Looking east from the wellbore. The well location is bare earth and gravel. The location is surrounded by cropland.



Photo 10. Looking north from the wellbore. See photo 9 comments.



Inspection Photos
Location Name: LINDA #1
Location ID: 317307



Photo 11. Looking west from the wellbore. See photo 9 comments.



Photo 12. Looking south from the wellbore. See photo 9 comments.