

# Final Reclamation and Stormwater Inspection

June 17, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 306343

Well Name: STATE-61N68W/16SWNW

Inspection Document #: 718600680

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE-61N68W/16SWNW  
Location ID: 306343



**Photo 1.** Looking South down the access road. The location and access road are in active cropland.



**Photo 2.** Picture taken at midpoint of access road. Access road and location appears to be primarily seeded with wheat. Surrounding cropland is a mix of rye and wheat.



Inspection Photos  
Location Name: STATE-61N68W/16SWNW  
Location ID: 306343



**Photo 3.** Looking south across the well location.



**Photo 4.** Looking south from the center of the wellbore area. Subsidence was not observed. The area is within active cropland.



Inspection Photos  
Location Name: STATE-61N68W/16SWNW  
Location ID: 306343



**Photo 5.** Looking east from wellbore. See photo 4 comments.



**Photo 6.** Looking north from wellbore. See photo 4 comments.

Inspection Photos  
Location Name: STATE-61N68W/16SWNW  
Location ID: 306343



**Photo 7.** Looking west from wellbore. See photo 4 comments.



**Photo 8.** Looking north from the south side of the well location. Some areas have reduced crop coverage.



Inspection Photos  
Location Name: STATE-61N68W/16SWNW  
Location ID: 306343



**Photo 9.** Looking south across the tank battery.



**Photo 10.** Looking west from the center of the tank battery near where the separator was located. Crop coverage is lower than the surrounding area.



Inspection Photos  
Location Name: STATE-61N68W/16SWNW  
Location ID: 306343



**Photo 11.** Looking south near the center of the tank batter. A natural gas pipeline sign is present.



**Photo 12.** Looking north across the tank battery location.

Inspection Photos  
Location Name: STATE-61N68W/16SWNW  
Location ID: 306343



**Photo 13.** Reference cropland to the west of the tank battery.



**Photo 14.** Photo from FIR 717300006 taken 08/13/2024. Indicating reclamation for recent excavations on location has undergone one growing season.