

Final Reclamation and Stormwater Inspection

June 16, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 335662

Location Name: SOSA A UNIT-61N68W/18NWNW

Inspection Document #: 718600686

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SOSA A
UNIT-61N68W/18NWNW
Location ID: 335662



Photo 1. Looking east down the access road. Very little desirable vegetation has established on the access road. List B noxious weed bull thistle is present on the access road (red circle).



Photo 2. Picture taken at mid point of access road looking east. Bare patches are present on the access road.



Inspection Photos
Location Name: SOSA A
UNIT-61N68W/18NWNW
Location ID: 335662



Photo 3. Looking east across the tank battery and location. Undesirable weeds curly dock, kochia and list C noxious weed field bindweed are present throughout the location.



Photo 4. Looking east across the location towards wellbores. No oil and gas equipment remains on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718600686

Inspection Photos
Location Name: SOSA A
UNIT-61N68W/18NWNW
Location ID: 335662



Photo 5. Looking east from well API 123-11698. There is little to no establishment of desirable perennial vegetation. Undesirable weeds curly dock, kochia and list C noxious weed field bindweed are present throughout the location.



Photo 6. Looking north from the well bore towards four other PA wellbores on location. See photo 5 comments.



Inspection Photos
Location Name: SOSA A
UNIT-61N68W/18NWNW
Location ID: 335662



Photo 7. Looking south from the wellbore. See photo 5 comments.



Photo 8. Looking west from the wellbore. See photo 5 comments.



Inspection Photos
Location Name: SOSA A
UNIT-61N68W/18NWNW
Location ID: 335662



Photo 9. Looking east across four PA wellbores on the north side of the location. See photo 5 comments.



Photo 10. Reference vegetation to the east of the well location.

