

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8630 Entrance to location



Photo # 8447 Wellhead lacks signage/not in compliance with CECMC rules

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8671 Location



Photo # 8706 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8732 SW corner of location



Photo # 8733 SE corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8734 NE corner of location



Photo # 8735 NW corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8699 Flow line heating insulation open ended/wildlife hazard available for entry by wildlife



Photo # 8703 Flow line heating insulation open ended/wildlife hazard available for entry by wildlife

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC NOLTE 14-44 PAD

Location ID: 334568

Date: 06/17/2025



Photo # 8704 Flow line heating insulation open ended/wildlife hazard available for entry by wildlife




Photo # 8707 Battery signage is not legible/not in compliance with CECMC rules