

Inspection Photos

Location Name: Simmons/42-20 Pad

Location #: 430104



Photo #1

Simmons 42-20D Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 430104



Photo #2

Simmons 42-20D Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Simmons/42-20 Pad

Location #: 430104



Photo #3

Simmons 42-20D Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #4

Simmons 42-20D Battery site

Inactive | Shut-down

ECD(s), Separator(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Simmons/42-20 Pad

Location #: 430104



Photo #5

Simmons 42-20D Battery site

Inactive | Shut-down

Battery sign



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Simmons/42-20 Pad

Location #: 430104

Associated Well(s)	API	Location	Status
1. Simmons 42-20D	123-36054	430104	SI

Photo #6

Simmons 42-20D Battery site

Inactive | Shut-down

Associated well(s)

1: Shut-In | SI



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources