

Inspection Photos
Location: Horsetail Gathering (30 CPB)
Location ID: 487246, Spill ID 487246



Photo 1 – Placard



**Photo 2 – Facing Northeast,
collapsed backfill**



**Photo 3 – Facing North, collapsed
backfill**



Inspection Photos
Location: Horsetail Gathering (30 CPB)
Location ID: 487246, Spill ID 487246



Photo 4 – Facing North, collapsed backfill



Photo 5 – Facing West collapsed backfill



Inspection Photos
Location: Horsetail Gathering (30 CPB)
Location ID: 487246, Spill ID 487246



Photo 6 – Stockpile and collapsed backfill



Photo 7 – Unlabeled Stockpile

